



Clerk Report Playpark Inspections September 2020

Introduction

Nash Mills Play Park at Bunkers Lane is checked weekly by our warden but to comply with our insurance recommendations we have a programme of annual and quarterly inspections carried out by qualified contractors.

We requested an additional quote for works following the Wicksteed and Rospa reports (attached) as RoSPA do not carry out repairs. The Sovereign quote and reports were delayed due to Covid-19 restrictions.

The reports vary in recommendation, however both RoSPA and Sovereign reports are recommending a similar degree of works, the equipment in-situ is mainly Kompan apparatus.

Company	Date of Inspection	High Risk faults detailed	Cost of Remedial Works Required Medium Faults only
Wicksteed	May 2019	None	£1444.91 plus vat
RoSPA	Jan 2020 & June 2020	None	n/a
Sovereign	July 2020	None	£1337.46 plus vat

Recommendation

Nash Mills Parish Council should instruct the completion of the medium risk works soon and within the next three months to comply with the risk assessment as recommended by Sovereign and then decide whether there is to be any upgrade to the other equipment following detailed consideration of all reports.

Decision Needed

Council to decide whether to take the clerks recommendation and to decide on contractor to appoint. It has not been possible to obtain 3 quotes as the clerk was unable to find anyone else to take on the survey but 3 reports have been obtained to quantify the degree of works required.

Appendices- Rospa/Wicksteed and Sovereign reports and quotes